

Inspection Report of Executive Engineer, Malleshwaram Division, Ward No.35, 36 & 45

Ward-36 & 45

Date:18/06/2010

Ward-35

Date:19/06/2010

Sl. No.	Details of Inspected works / Problems	Inspection Reports	Sujetions to Solve the Problems	Concerned Department	Remarks
1	Construction of Road side drain at site No.27-28, I.T.I. layout in ward No.35	Is found that water is standing and work has to be taken up	Land acquisitin is under process already notified in the Gazette	D.C (Estate)	
2	Re-construction of Janatha Bazar in Sadashivanagar Ward No.35	Reconstruction is required as building is old	The Administraction Department as agreed to vacate the building sanction is required	AEE (Mathikere) Sub-division	
3	Inspection of Individual houses at Puttaiah Compound in ward no.35 under 22.75% grants	Work is under progress instructed to construct according to approved plan	Work will be carried out according to sanction plan	AEE (Mathikere) Sub-division	
4	RMV layout Park Ward No.35	Rain harvesting to be done	Action will be tken to implement Rain harvesting.	AEE (Mathikere) Sub-division	
5	East-West Park Malleshwaram Ward No.35	Improvement Park & Rain harvesting to be done	Action will be tken to implement Rain harvesting & to improve the park	AEE (Mathikere) Sub-division	
6	Sankey tank park Ward No.35	Rain harvesting to be done	Action will be tken to implement Rain harvesting.	AEE (Mathikere) Sub-division	
7	A.G.S. layout Ward No.35	Improvement Park & Rain harvesting to be done	Action will be tken to implement Rain harvesting & to improve the park	AEE (Mathikere) Sub-division	
8	Inspected Bathroom point & collection point near BBMP office Garbage found to be in large quantity in ward no.36	Environamental Officer told that the garbage worker's are on strike for last 7 days. Hence, garbage was not cleared.	It is found that worker's are on duty and to instruct the garbage contractor to clear the garbage immediately	Environamental Officer, Mathikere Sub-division	

9	4th cross, Nethaji nagar, Mathikere in ward no.36	Silt not removed in the side drains	Instructed AEE to engage gangman remove the silt's in side drain and to allow free flow of water.	AEE (Mathikere) Sub-division	
10	Railway parallel road near foot bridge in ward no.36	Lot of Garbage was found Senior Health Inspector told that garbage was not removed since 7days	Instructed to personally inspect and clear the garbage at the earliest 2 days bill amount may be cut from contractor's bill.	Environmental Officer, Mathikere Sub-division	
11	Railway parallel road in ward no.36	The vegetation & plants are grown along the storm water drain. The HFL was not marked on SWD	Instructed AEE to take action to remove the plantation and to mark HFL all along storm water drain at 50mtrs interval.	AEE (Mathikere) Sub-division	
12	Pig shed in BBMP Office Road, in ward no.36	found that lot of noise and un hygieness near the pig shed	Instructed to give notice	Environmental Officer, Mathikere Sub-division	
13	Burrial ground and vacant land of Prathamesh apartment in ward no.36	Ownership and Extent area of the Burrial ground was not known to Revenue Officer. Burrial ground shabby and lot of vegetation is observed. The compound was found to be collapsed	ARO (Mathikere) instructed keep the records of Burrial ground like extent ownership etc., AEE (Mathikere) has to take action to improve Burial ground and a construct the boundary compound	AEE (Mathikere) Sub-division, ARO (Mathikere) Sub-division	
14	Sanjeevappa Garden in ward no.36	Community hall construction was nearing completion it is told that one Sri.Raghava reddy voluntarily handed over the site of dimension 30 x 42 ft to BBMP	It is instructed to regularize the records and to enter to make a entry in the property register of BBMP.	AEE (Mathikere) Sub-division	
15	Sanjeevappa Garden in ward no.36	Houses for SC/ST under 22.75% grants was under progress the work was found to be slow.	Instructed to speedup the work agency may intimated in this regards	AEE (Mathikere) Sub-division	

16	1st main, Nethaji nagara in ward no.36	Large dia mtr pipes are found on the road it is informed that BWSSB is planning to lay the pipes for waste management	Instructed to write a letter to BWSSB to take permission and finish the work at the earliest	AEE (Mathikere) Sub-division	
17	MSR Road, Near Ayyappa Temple in ward no.36	BESCOM work of erecting electric pole was under progress it is found that pole is being erected in the middle of side drain obstructing flow of rain water	Instructed AE, BESCOM not to put the poles in the side drain. AEE should look after	AEE (Mathikere) Sub-division	
18	Inspection Individual houses at K.N.Extn., Subedarpalya in ward no.45 under 22.75% grants	Instructed to Complete the work within one month	Instructions given to Contractor to speed up the work & within one month	AEE (Mathikere) Sub-division	
19	Culverts at 8th & 9th main of Subedarpalya, K.N.Extension in ward No.45	The culvert was found to be old, top level of the culvert was not in level	Instructed to Re-construct the culvert	AEE (Mathikere) Sub-division	
20	Construction of Road side drain at 6th main K.N.Extn., Subedarpalya in ward No.45	The culvert was found to be old, top level of the culvert was not in level	Instructed to Re-construct the culvert	AEE (Mathikere) Sub-division	
21	Karimandi Slum and Byrahanumaiah Slum in ward no.45	Houses in this slum are found to be in delebarated condition & slum dwellers are found to be living in very small areas	Instructed to construct the Residential G+3 Apartments under the BSUP JNN URM scheme with concent of slum dwellers	AEE (Mathikere) Sub-division	
22	Siddartha Slum, Shariff Slum in ward no.45	Houses in this slum are found to be in delebarated condition.	Works to be taken up under 22.75% grants for construction of Individual Pakka houses	AEE (Mathikere) Sub-division	

23	RTO Complex Building, Yeshwanthpur in ward no.45	Damaged portion of the compound to the left side of RTO Complex	Works to be taken immediately & Estimate for full length of compound (including damage & existing length) is to be submitted for approval	AEE (Mathikere) Sub-division	
24	Vehicle parking at Yeshwanthpur RTO complex premises in ward no.45	The vehicles are being collected parking charges even though tender is period expired.	Instructed to stop the parking charges collection immediately		
25	Anganwadi Building & Tailoring Center at Shariff slum in ward no.45	The Anganwadi Building found to be debarated condition.	Instructed to take action for construction of Anganwadi & tailoring hall	AEE (Mathikere) Sub-division	
26	Secondary drain behind 9th cross Gokula 1st stage 2nd phase in ward no.45	Drain found to encroached by the Resident's on either side.	Instructed to give a notice to the Residents who encroach the Secondary drain.	AEE (Mathikere) Sub-division	

1.Officer's Present :Dr. Shiva Prasad / Muniswamy Gowda/Jaypal, Corporator W-35, 36 &45, Deputy Commissioner (Welfare), Superintendent Engineer, Executive Engineer, Assistant Executive Engineer (Mathikere), Assistant Revenue Officer (Mathikere), Environmental Officer (Mathikere) Assistant/Junior Engineer & Senior/Junior Health Inspector.

BRUHATH BANGALORE MAHANAGARA PALIKE
Executive engineer, mallechwaram, division, inspection report of ward No.64, Rajmahal; Guttahalli

Date: 16/06/2010.

Sl No.	Details of inspected works	Points observed during inspection	Suggestions given to solve the problems	Whom to be directed to take Action	Remarks
1	Tailoring Class at Raj Mahal Guttahalli ward no.64	The training programme in Tailoring Hall was inspected & it was observed that Problem regarding Electrification	It has been directed to repair the electrical problem & has been suggested to replace the burnt out tube lights.	Executive Engineer (BESCOM) mallechwaram	
2	Regarding BBMP property 10th Cross Bhandavayanagara Raj Mahal Guttahalli ward no.64	It has been observed that there is no protection around the property. It has been told that legal hurdle in court has been settle in favour of BBMP	It has been directed to protect the property by proper chain link fencing & to fix the BBMP Name Board	Assistant Executive Engineer(Mallechwaram)	
3	Regarding Corner property at 8th Main road Vyalikaval Raj Mahal Guttahalli ward no.64	Enquiry has been done regarding Tax Payment	It has been directed to issue notice to the concerned to the pay the property Tax. It has been instructed to take action to shift the food & civil Supply Office Building since parking problem is causing nuisance to the local residences.	Assistant Revenue Officer (Mallechwaram)	
4	Regarding Open air Theatre & park at 12th Cross Raj Mahal Guttahalli ward no.64	It has been noticed that there is no pathway inside the park which is situated behind BBMP open air theatre	It has been directed to take action regarding construction of Pathway, Water supply & sanitary works inside Park, also it has been directed to raise the height of chainlink fencing. Also it has been instructed to clear the stocked debries outside the open air theatre	Horticulture Superdindent (Mallechwaram), Assistant Executive Engineer(mallechwaram)	
5	Regarding storm water drain at 10th cross Raj Mahal Guttahalli ward no.64	It has been noticed that several cracks are exisiting in size stone measonry culvert. Cart parking stand spot was inspected	It has directed to take immidiate action to repair the retaining wall of culvert, also proper action regarding parking of 2 wheelers Stand inside the cart stand It has been instructed to Shift the fodder sellers & to maintaine the cleanliness of that premises	Assistant Executive Engineer(Mallechwaram)	

6	Construction of individual houses under 22.75 Grant at Jabbar Block Raj Mahal Guttahalli ward no.64	Individual houses work has been inspected in Jabbar Block	It has been instructed to fix the Name board in front of individual houses	Assistant Executive Engineer(Malleswaram)	
7	Regarding football Ground & Park at Lower Palace Archid Raj Mahal Guttahalli ward no.64	Football Ground & park has been inspected	It has been directed to request local councilor to write a letter to J.C (West) regarding construction steel truss to western side ground	Executive Engineer Project (West)	
			It has been directed to widen the existing path way in Park which is situated at 1st Main of lower Palace orchid	Horticulture Superdindent (Malleshwaram),	

BRUHATH BANGALORE MAHANAGARA PALIKE
Executive engineer, malleshwaram, division, inspection report of ward No.65, Kadu Malleshwara.

Date: 15/06/2010.

Sl No.	Details of inspected works	Points observed during inspection	Suggestions given to solve the problems	Whom to be directed to take Action	Remarks
1	Providing rain water harvesting and improvements to footpath in pit Ground of Kadu Malleshwara ward No.65	It has been observed that the work is going on in snail pace	It has been directed to complete the work within stipulated time since the monsoon has begun	Executive Engineer Project (West)	
2	Construction of Shed & Installation of Organic waste converter at 13th Cross of Malleshwaram Market in Ward No.65	The methodology of functioning of organic waste converter has been observed. It has been discussed regarding mennure which is generated from OWC can be divided & packed in the form of 5, 10 & 20K.G's Bags.	Collective dicission has taken to open a small shop inside the market area for marketing of mennure produceed by OWC	AEE (Malleshwaram) Sub-Division	
3	Desilting of drain at 8th Cross of kadu Malleshwara in ward No.65	Desilting work of tertiary drain has been inspected, it was noticed that desilting at CD points has not been done.	It has been directed to remove the BS Slabs of cross drainage & Desilt the area of Drain	AEE (Malleshwaram) Sub-Division	

4	Providing & installation of modern Washing machinery at Dhobi Ghat in ward No.65	The methodology of functioning of modern Washing machineries has been keenly observed. It has been noticed that there is no Shelter to generator which is installed inside the compound. Also it was observed that there is no proper methodology adapting for drying of clothes. it has been noticed that the delay in implementing rain water harvesting. it has been observed that laxity in maintaining proper cleanliness inside the premises of Dhobi Ghat.	It has been directed to submit the estimate for providing shelter to generator. Also direction has given to use iron poles with hooks for drying purpose. Health authorities directed to maintain proper cleanliness everyday. It has been directed to speed up the Rain Water harvesting Scheme.	AEE (Malleshwaram) Sub-Division & Environment Officer (malleshwaram) & AEE project (West)	
5	Construction of Storm water drain at 11th Main, 11th B Cross Malleshwaram in ward No.65.	It has been observed that the size stone masonry of SWD is in dilapidated condition. Also it was noticed that private building is coming up by the side of SWD and possibility of builder encroaching the SWD	It has been directed to SWD authorities to take up Construction work to SWD & to check the possibility of encroachment private builder	Executive Engineer, Storm water Drain wing	

Executive engineer, mallechwaram, division, inspection report of ward No.66, Subramanyanagara

Date: 15/06/2010.

SI No.	Details of inspected works	Points observed during inspection	Suggestions given to solve the problems	Whom to be directed to take Action	Remarks
1	Improvement to drain at Sangolli Rayan Park	It has been noticed that there is no proper bed slope provided	It has been instructed to give proper bed slope pertaining to construction of secondary drain & has been directed to take action regarding quality of work ensuring proper technical specification	Assistant Executive Engineer (Mallechwaram)	
2	Construction of Storm water Drain inside Sangolli Rayana Park	Incomplete storm water drain work has been inspected	It has been instructed to take action against concerned contractor towards completion of work	Storm water drain wing	
3	Construction of SC/St Houses at A block Subramanyanagara	It has been observed that proper name board has not been installed in front of individual houses	Instruction has given to the concerned authorities to fix the proper name board indicating head of account, Engineers & contractors name with BBMP logo in front of all the individual houses	Assistant Executive Engineer (Mallechwaram)	
4	Regarding Garbage collection point at 9th cross of B block subramanyanagara	It has been observed that laxity in maintaining proper hygienic around the collection Point	It has been instructed to maintain hygienic	Environment Engineer	
4	Storm water drain 5th Main Ward No.76 Gayathrinagra	Spot has been inspected & observed the dilapidated condition of Storm water drain & lack of proper fencing	It has been directed to repair SWD & to replace Broken BS slab	Executive Engineer SWD	
			It has been instructed to take up chain link fencing work to protect the property from encroachers	Assistant Executive Engineer (Mallechwaram)	
5	Garbage Collection Point 5th Main D block Gayathrinagara	It has been observed that there was no proper cleaning around garbage collection point	It has been instructed to maintain hygienic and cleanliness around collection point	Environment Officer	
6	Construction of individual houses under 22.75% grant	Spot has been inspected	it has been directed to maintain quality of work and to ensure proper technical specification. It has been instructed to fix Name Board in front all houses	Executive Engineer (Mallechwaram)	

During inspection the following Officer's were Present Smt. Chethana Gowda Councilor ward No.66, Subramanyanagara, Deputy Commissioner